

No. CEO-CHB/2021/PA/63

Dated: 01.05.2021

PRESS RELEASE

Considering incidents of fire in some of the hospitals in other parts of the Country especially due to sudden increase in consumption of oxygen, Hon'ble Governor and Administrator UT, Shri V.P. Singh Badnore has directed to be extra careful about the fire issues.

Today (01.05.2021) all the fire hydrants at Hospital- Sector-48 were tested. A Mock Drill of fire sensing was also carried out. All the fire extinguishers have been checked, refilled and re-validated.

Similarly, during last week, all the fire hydrants at GMCH-32 were tested. A Mock Drill of fire sensing was also carried out. All the fire extinguishers have been checked, refilled and re-validated.

All the medical and para-medical staff have also been sensitised to ensure that:

- All the fire-exits should remain clear all the time and should not be blocked by the idle stretchers/trolleys.
- All the oxygen points to be got checked from some technician to ensure there is no leakage and are properly closed after use.


(Yashpal Garg, IAS)

Incharge COVID Management
GMCH-32, Chandigarh